	Hits	Search Text	DBs
82	61941	diamond or PCD or PCBN or	EPO; JPO; DERWENT;
		CBN or boron adj nitride	IBM_TDB
83	316410	shrinkage or stress or constraint	EPO; JPO; DERWENT;
			IBM_TDB
84	16358	WC or tungsten adj carbide	EPO; JPO; DERWENT;
			IBM_TDB
85	90	S82 and S83 and S84	EPO; JPO; DERWENT;
			IBM_TDB
86	6305	cemented adj carbide	EPO; JPO; DERWENT;
			IBM_TDB
87	2648	S82 and (S84 or S86)	EPO; JPO; DERWENT;
			IBM_TDB
88	573378	density or porosity	EPO; JPO; DERWENT;
			IBM_TDB
89	109	S87 and S88	EPO; JPO; DERWENT;
			IBM_TDB
90	3410	densified	EPO; JPO; DERWENT;
			IBM_TDB
91	46	S82 and S90	EPO; JPO; DERWENT;
			IBM_TDB
92	840649	cutting or drill or bit	EPO; JPO; DERWENT;
			IBM_TDB
93	876220	cutting or drill or bit or drilling	EPO; JPO; DERWENT;
			IBM_TDB
94	3569616	sinter\$3 or temp or temperature or	
		- -	IBM_TDB
95	759	S82 and (S84 or S86) and S93 and S94	
			IBM_TDB
96	731	177111111701	EPO; JPO; DERWENT;
			IBM_TDB
97	703	S96 not S89	EPO; JPO; DERWENT;
			IBM_TDB
98	702	S97 not S91	EPO; JPO; DERWENT;
			IBM_TDB

	Hits	Search Text	DBs
99	2	1"(1325 /(135"	EPO; JPO; DERWENT; IBM_TDB